


# New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty  
Commissioner

## DAILY INSPECTION REPORT

<b>Site Code #:</b> 7-55-08	<b>Date:</b> January 8, 2004	<b>Report #:</b> NYSEG010804
-----------------------------	------------------------------	------------------------------

**Site Name:** NYSEG Ithaca Court St.

**Location:** Ithaca, Chemung County

**NYSEG Proj. Mgr.:** Bert Finch

**DEC Proj. Mgr.:** Bill Ottaway

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson Environmental

**Site Phone & Fax:**

	AM	PM
<b>Weather</b>	Overcast, Lt. Snow	Overcast
<b>Temperature</b>	10 degrees	20 degrees
<b>Wind Direction</b>	NW	NW

### Description of work performed by contr. this report period:

- Completed service to #602 W.Court St. Impacted material removed to 7 feet bgs from 2 feet north of water main to 1 foot south of Duct #2; then to 6 feet bgs from 1 foot south of Duct #2 to 1 foot north of Duct #1.
- Removed 7 feet of Duct #1, Duct #2, and storm sewer.
- Sent 3 trucks to ESMI.

### Description of inspections performed by engr. this report period:

- 

### Discussions/comments regarding visitors, contractor and/or engineer:

- 

### Change Orders:

- 

### Sampling and Analyses:

•

Major Issues	Description & Reason

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

**Contractor's Information:**

Prime contractor worked from 7:00A to 9:00P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	2			

**Site Representative:** R. Scott Deyette

**Date:** January 8, 2004

**Representative's signature:**

**Reviewed By:**

**Date:**