

**New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty  
Commissioner

**DAILY INSPECTION REPORT**

<b>Site Code #:</b> 7-55-08	<b>Date:</b> January 12, 2004	<b>Report #:</b> NYSEG011204
-----------------------------	-------------------------------	------------------------------

**Site Name:** NYSEG Ithaca Court St.

**Location:** Ithaca, Chemung County

**NYSEG Proj. Mgr.:** Bert Finch

**DEC Proj. Mgr.:** Bill Ottaway

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson Environmental

**Site Phone & Fax:**

	<b>AM</b>	<b>PM</b>
<b>Weather</b>	Overcast, Lt. Snow	Overcast, Lt. Snow
<b>Temperature</b>	25 degrees	31 degrees
<b>Wind Direction</b>	NW	NW

**Description of work performed by contr. this report period:**

- Removed 18 feet of Duct #1. Impacted material removed to 6.5 feet bgs from 4 feet north of duct to 2 feet south of duct.
- Removed 18 feet of storm sewer.
- Sent 2 trucks to ESML.

**Description of inspections performed by engr. this report period:**

- 

**Discussions/comments regarding visitors, contractor and/or engineer:**

- 

**Change Orders:**

- 

**Sampling and Analyses:**

-

Major Issues	Description & Reason

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

**Contractor's Information:**

Prime contractor worked from 7:00A to 6:00P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	2			

**Site Representative:** R. Scott Deyette

**Date:** January 12, 2004

**Representative's signature:**

**Reviewed By:**

**Date:**

REVISED 5/99 @BLANK.wpd