

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty
Commissioner

DAILY INSPECTION REPORT

Site Code #: 7-55-08	Date: January 19, 2004	Report #: NYSEG011904
-----------------------------	-------------------------------	------------------------------

Site Name: NYSEG Ithaca Court St.

Location: Ithaca, Chemung County

NYSEG Proj. Mgr.: Bert Finch

DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.:

Proj. Contr.: Severson Environmental

Site Phone & Fax:

	AM	PM
Weather	Overcast, Lt. Snow	Overcast, Lt. Snow
Temperature	10 degrees	18 degrees
Wind Direction	NW	NW

Description of work performed by contr. this report period:

- Removed 8 feet of Duct #1. Impacted material removed to 6 feet bgs from north curb to the sidewalk (5 feet).
- Removed 8 feet of storm sewer.
- Sent 2 trucks to ESML.

Description of inspections performed by engr. this report period:

-

Discussions/comments regarding visitors, contractor and/or engineer:

-

Change Orders:

-

Sampling and Analyses:

-

Major Issues	Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 5:00P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	2			

Site Representative: R. Scott Deyette

Date: January 19, 2004

Representative's signature:

Reviewed By:

Date:

