


New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty
Commissioner

DAILY INSPECTION REPORT

Site Code #: 7-55-08	Date: January 20, 2004	Report #: NYSEG012004
-----------------------------	-------------------------------	------------------------------

Site Name: NYSEG Ithaca Court St.

Location: Ithaca, Chemung County

NYSEG Proj. Mgr.: Bert Finch

DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.:

Proj. Contr.: Severson Environmental

Site Phone & Fax:

	AM	PM
Weather	Overcast	P. Sunny
Temperature	10 degrees	15 degrees
Wind Direction	NW	NW

Description of work performed by contr. this report period:

- Completed water service to #602 W. Court St.. Removed material down to 3.5 feet bgs from sewer main to 2 feet north of water main. From 2 feet north of water main to 2 feet south of Duct #1, material removed down to 7 feet bgs. From 2 feet south of Duct #1 to 2 feet north of Duct, material removed down to 5 feet bgs. Total trench width of 5 feet.
- Sent 2 trucks to ESMI.

Description of inspections performed by engr. this report period:

-

Discussions/comments regarding visitors, contractor and/or engineer:

-

Change Orders:

-

Sampling and Analyses:

•

Major Issues	Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 5:30P.

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	Personnel	P	1	2	3
Daewoo 135 Backhoe	1				Site Supervisor	1			
Air Handling Equipment	1				Operator	2			
					Laborer	2			

Site Representative: R. Scott Deyette

Date: January 20, 2004

Representative's signature:

Reviewed By:

Date: