# New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Bureau of Construction Services Field Support Unit



## DAILY INSPECTION REPORT

Site Code #: 7-55-008 Date: May 12, 2004 Report #: NYSEG051204
--

Site Name: NYSEG Ithaca Court St.- Wooden Duct Removal Location: Ithaca, Tompkins County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway Consultant Proj. Mgr.: Dave Budosh Proj. Contr.: Sevenson Site Phone & Fax:

	AM	РМ			
Weather	sunny	sunny			
Temperature	66				
Wind Direction	SSE - 2 mph	S - 2 mph			

#### **Description of work performed by contr. this report period:**

• Contractor excavated material from curb line to sidewalk on the north side of Court St. in front of #512 Court St. Excavated a wooden duct, both containing tar, and surrounding soils. Clay tile pipe previously seen accompanying duct was not present. Excavation to 12' below road surface, due to the presence of tar fingers in underlying clay.

Description of inspections performed by engr. this report period:

**Discussions/comments regarding visitors, contractor and/or engineer:** 

Bert Finch on site today.

**Change Orders:** 

•

**Sampling and Analyses:** 

•

Major Issues	Description & Reason	
None.		

### Health & Safety:

Level of protection: D. Is the level of protection in conformance with the approved Health & Safety Plan? Yes. List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone			

## **Contractor's Information:**

Prime contractor worked from 7:00A to 5:00P.

Subcontractor	Activity	Hours Worked			
PAGE	hauling waste				

Equipment	Р	1	2	3	Personnel	Р	1	2	3
Komatsu W140 backhoe, with hoe-ram	1				Supervisor	1			
Komatsu PW170ES excavator	1				Operator	2			
Tractor trailer		4			Laborer	2			
Loader	1				Teamster		4		
Vac truck	1				Health & Safety	1			

NYSDEC Site Representative: Eric S. Knapp

Date: May 12, 2004

**Representative's signature:** 

**Reviewed By:** 

Date:

REVISED 5/99 @BLANK.wpd