## **New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office Bureau of Construction Services Field Support Unit



#### DAILY INSPECTION REPORT

| Site Code #: 7-55-008  | <b>Date:</b> May 20, 2004   | Report #: NYSEG052004  |
|------------------------|-----------------------------|------------------------|
| Site edge III / 22 000 | <b>Dutce</b> 1/10 20, 200 1 | report # 1 (182002200) |

Site Name: NYSEG Ithaca Court St.- Wooden Duct Removal

Location: Ithaca, Tompkins County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.: Dave Budosh

**Proj. Contr.:** Sevenson **Site Phone & Fax:** 

|                | AM         | PM          |
|----------------|------------|-------------|
| Weather        | cloudy     | sunny       |
| Temperature    | 59         | 74          |
| Wind Direction | SW - 3 mph | SSE - 6 mph |

### Description of work performed by contr. this report period:

• Contractor excavated material from north side of Court St., from edge of pavement to north of sidewalk, in front of #508 Court St. Excavated wooden duct, clay tile sewer pipe, and associated soils, to a depth of 9 feet. A lense of gravel containing NAPL is observable heading to the north, beyond our ability to remove it today. We will resume tomorrow.

# **Description of inspections performed by engr. this report period:**

•

**Discussions/comments regarding visitors, contractor and/or engineer:** 

## **Change Orders:**

\_

#### **Sampling and Analyses:**

| Major Issues | Description & Reason |
|--------------|----------------------|
|              |                      |

# **Health & Safety:**

Level of protection: D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

| Site Visitors | Representing | Entered Exclusion Zone |
|---------------|--------------|------------------------|
|               |              |                        |

# **Contractor's Information:**

Prime contractor worked from 7:00A to 5:00P.

| Subcontractor | Activity      | Hours Worked |
|---------------|---------------|--------------|
| PAGE          | hauling waste |              |

| Equipment                                | P | 1 | 2 | 3 | Personnel       | P | 1 | 2 | 3 |
|--|---|---|---|---|-----------------|---|---|---|---|
| Komatsu W140<br>backhoe, with<br>hoe-ram | 1 |   |   |   | Supervisor      | 1 |   |   |   |
| Komatsu<br>PW170ES<br>excavator          | 1 |   |   |   | Operator        | 2 |   |   |   |
| Tractor trailer                          |   | 4 |   |   | Laborer         | 2 |   |   |   |
| Loader                                   | 1 |   |   |   | Teamster        |   | 4 |   |   |
| Vac truck                                | 1 |   |   |   | Health & Safety | 1 |   |   |   |

| <b>NYSDEC Site Representative:</b> | Eric S. Knapp | <b>Date:</b> May 20, 2004 |
|------------------------------------|---------------|---------------------------|
| Representative's signature:        |               |                           |

| Reviewed By:  | Date: |
|---------------|-------|
| iteriewed by. | Dutc. |