New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Remedial Bureau C Section D



DAILY INSPECTION REPORT

Site Name: NYSEG Ithaca Court St. Location: Ithaca, Chemung County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.:

Proj. Contr.: Sevenson Environmental

Site Phone & Fax:

	AM	PM
Weather	P. Sunny	P. Sunny
Temperature	55 degrees	65 degrees
Wind Direction		

Description of work performed by contr. this report period:

- Removed 55 feet of clay tile pipe. Removed material down to 3 feet bgs, and 2 feet north and south of pipe. Material continues to be heavily stained, tar present, strong odor. Started at #502 Court St., moving east toward intersection of Court and Park.
- Uncovered a 3 x 4 foot brick structure (similar to one found at Washington and Court St. intersection). Clay tile pipe enters at west and exits at east. Pipe on east side appears to be a larger diameter (about 10 inches). Tar noted within structure. Top of structure at about 2 feet bgs, and bottom below the excavation depth (3-3.5 feet bgs). Located on west side of intersection.
- Sent 3 trucks to ESMI.

<u>Description of inspections performed by engr. this report period:</u>

• Dave Budosh (URS) onsite.

<u>Discussions/comments regarding visitors, contractor and/or engineer:</u>

Sampling and Analyses:

.

•

Major Issues	Description & Reason	

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00A to 3:30P.

Site Representative: R. Scott Deyette Date: May 28, 2004

Representative's signature:

REVISED 5/99 @BLANK.wpd