New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Bureau of Construction Services Field Support Unit



DAILY INSPECTION REPORT

Site Code #: 7-55-008	Date: June 1, 2004	Report #: NYSEG060104
-----------------------	---------------------------	-----------------------

Site Name: NYSEG Ithaca Court St.- Wooden Duct Removal

Location: Ithaca, Tompkins County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.: Dave Budosh

Proj. Contr.: Sevenson **Site Phone & Fax:**

	AM	PM
Weather		
Temperature		
Wind Direction		

Description of work performed by contr. this report period:

• Contractor excavated material from north side of Court St., in front of credit union near Meadow St., to a depth of 7.5'. This completed this portion of the excavation.

<u>Description of inspections performed by engr. this report period:</u>

<u>Discussions/comments regarding visitors, contractor and/or engineer:</u>

Change Orders:

•

Sampling and Analyses:

•

Major Issues	Description & Reason

Health & Safety:

Level of protection: D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone			

Contractor's Information:

Prime contractor worked from 7:00A to 5:00P.

1

Subconti	Subcontractor			Activity		Hours Worked			
PAG	E		hauling waste						
Equipment	P	1	2	3	Personnel	P	1	2	3
Komatsu W140 backhoe, with hoe-ram	1				Supervisor	1			
Komatsu PW170ES excavator	1				Operator	2			
Tractor trailer		4			Laborer	2			
Loader	1				Teamster		4		

NYSDEC Site Representative:	Eric S. Knapp	Date: June 1, 200	4
Representative's signature:			
Reviewed By:		Date:	

Health & Safety

1

Vac truck