### **New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office Bureau of Construction Services Field Support Unit



#### DAILY INSPECTION REPORT

<b>Site Code #:</b> 7-55-008	<b>Date:</b> June 2, 2004	Report #: NYSEG060204
------------------------------	---------------------------	-----------------------

Site Name: NYSEG Ithaca Court St.- Wooden Duct Removal

Location: Ithaca, Tompkins County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway

Consultant Proj. Mgr.: Dave Budosh

**Proj. Contr.:** Sevenson **Site Phone & Fax:** 

	AM	PM
Weather		
Temperature		
Wind Direction		

### **Description of work performed by contr. this report period:**

• Contractor excavated material from north side of Court St., in front of #508, including excavating to allow replacement of sewer and water laterals. A sudden downpour filled excavation with runoff, but contractor was able to pump water from excavation and continue.

# **Description of inspections performed by engr. this report period:**

**Discussions/comments regarding visitors, contractor and/or engineer:** 

# **Change Orders:**

•

### **Sampling and Analyses:**

•

Major Issues	Description & Reason	

### **Health & Safety:**

Level of protection: D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone		

# **Contractor's Information:**

Prime contractor worked from 7:00A to 5:00P.

Subcontractor	Activity	Hours Worked
PAGE	hauling waste	

Equipment	P	1	2	3	Personnel	P	1	2	3
Komatsu W140 backhoe, with hoe-ram	1				Supervisor	1			
Komatsu PW170ES excavator	1				Operator	2			
Tractor trailer		7			Laborer	2			
Loader	1				Teamster		7		
Vac truck	1				Health & Safety	1			

<b>NYSDEC Site Representative:</b> Eric S. Knapp	<b>Date:</b> June 2, 2004	
Representative's signature:		
Reviewed By:	Date:	