New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Bureau of Construction Services Field Support Unit



DAILY INSPECTION REPORT

Site Code #: 7-55-008 Date: June 17, 2004 Report #: NYSEG061704

Site Name: NYSEG Ithaca Court St.- Wooden Duct Removal Location: Ithaca, Tompkins County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway Consultant Proj. Mgr.: Dave Budosh Proj. Contr.: Sevenson Site Phone & Fax:

	AM	РМ
Weather		
Temperature		
Wind Direction		

Description of work performed by contr. this report period:

• Contractor excavated material from north side of Court St., from curb line to sidewalk. Contractor removed duct #1, and a small dia. clay pipe, along with soils. Material removed to a depth of 7 feet.

•

Description of inspections performed by engr. this report period:

•

Discussions/comments regarding visitors, contractor and/or engineer:

Change Orders:

•

Sampling and Analyses:

Bottom sample and sidewall sample collected.

Major Issues	Description & Reason

Health & Safety:

Level of protection: D. Is the level of protection in conformance with the approved Health & Safety Plan? Yes. List deviations. Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone				

Contractor's Information:

Prime contractor worked from 7:00a to 5:00P.

Subcontractor	Activity	Hours Worked
PAGE	hauling waste	

Equipment	Р	1	2	3	Personnel	Р	1	2	3
Komatsu W140 backhoe, with hoe-ram	1				Supervisor	1			
Komatsu PW170ES excavator	1				Operator	2			
Tractor trailer		4			Laborer	4			
Loader	1				Teamster		4		
Vac truck	1				Health & Safety	1			

NYSDEC Site Representative: Eric S. Knapp

Date: June 17, 2004

Representative's signature:

Reviewed By:

Date:

REVISED 5/99 @BLANK.wpd