New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office Bureau of Construction Services Field Support Unit



DAILY INSPECTION REPORT

Site Code #: 7-55-008 Date: June 24, 2004 Report #: NYSEG062404

Site Name: NYSEG Ithaca Court St.- Wooden Duct Removal Location: Ithaca, Tompkins County NYSEG Proj. Mgr.: Bert Finch DEC Proj. Mgr.: Bill Ottaway Consultant Proj. Mgr.: R. Fudeman Proj. Contr.: Sevenson Site Phone & Fax:

	AM	РМ
Weather		
Temperature		
Wind Direction		

Description of work performed by contr. this report period:

• Contractor excavated material from north side of Court St., from center line to curb, in intersection with Park Place. Contractor removed duct #2 and a small dia. clay pipe, along with soils. Material removed to a depth of 10.5 feet. Contractor also excavated on south side of Court St. to provide services to 607 Court St.

Description of inspections performed by engr. this report period: •

<u>Discussions/comments regarding visitors, contractor and/or engineer:</u> NYSEG field inspector is a substitute for Dave Budosh, who is away for the week. <u>Change Orders:</u>

•

Sampling and Analyses:

•

Major Issues	Description & Reason

Health & Safety:

Level of protection: D. Is the level of protection in conformance with the approved Health & Safety Plan? Yes. List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Prime contractor worked from 7:00a to 5:00P.

Subcontractor	Activity	Hours Worked			
PAGE	hauling waste				

Equipment	Р	1	2	3	Personnel	Р	1	2	3
Komatsu W140 backhoe, with hoe-ram	1				Supervisor	1			
Komatsu PW170ES excavator	1				Operator	2			
Tractor trailer		5			Laborer	6			
Loader	1				Teamster		5		
Vac truck	1				Health & Safety	1			

NYSDEC Site Representative: Eric S. Knapp

Date: June 24, 2004

Representative's signature:

Reviewed By:

Date:

REVISED 5/99 @BLANK.wpd