



Erin Crotty  
 Commissioner

**DAILY INSPECTION REPORT**

|                              |                            |                              |
|------------------------------|----------------------------|------------------------------|
| <b>Site Code #:</b> 7-55-008 | <b>Date:</b> June 28, 2004 | <b>Report #:</b> NYSEG062804 |
|------------------------------|----------------------------|------------------------------|

**Site Name:** NYSEG Ithaca Court St.- Wooden Duct Removal  
**Location:** Ithaca, Tompkins County  
**NYSEG Proj. Mgr.:** Bert Finch  
**DEC Proj. Mgr.:** Bill Ottaway  
**Consultant Proj. Mgr.:** Dave Budosh  
**Proj. Contr.:** Sevenson  
**Site Phone & Fax:**

|                       | AM | PM |
|-----------------------|----|----|
| <b>Weather</b>        |    |    |
| <b>Temperature</b>    |    |    |
| <b>Wind Direction</b> |    |    |

**Description of work performed by contr. this report period:**

- Contractor excavated material from north side of Court Street within the intersection with Park Place, in order to remove existing wooden ducts and clay pipes containing tar, along with surrounding, contaminated soils. Contaminated soils were removed to a depth of 11.5 feet. A second crew replaced services for #126 Washington St. and #315 Meadow.
- 

**Description of inspections performed by engr. this report period:**

- 

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Change Orders:**

- 

**Sampling and Analyses:**

- 

| Major Issues | Description & Reason |
|--------------|----------------------|
|              |                      |

**Health & Safety:**

Level of protection: D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

| Site Visitors | Representing | Entered Exclusion Zone |
|---------------|--------------|------------------------|
|               |              |                        |

**Contractor's Information:**

Prime contractor worked from 7:00 a.m. to 5:00 p.m.

| Subcontractor | Activity      | Hours Worked |
|---------------|---------------|--------------|
| PAGE          | hauling waste |              |

| Equipment                          | P | 1 | 2 | 3 | Personnel       | P | 1 | 2 | 3 |
|------------------------------------|---|---|---|---|-----------------|---|---|---|---|
| Komatsu W140 backhoe, with hoe-ram | 1 |   |   |   | Supervisor      | 1 |   |   |   |
| Komatsu PW170ES excavator          | 1 |   |   |   | Operator        | 2 |   |   |   |
| Tractor trailer                    |   | 4 |   |   | Laborer         | 5 |   |   |   |
| Loader                             | 1 |   |   |   | Teamster        |   | 4 |   |   |
| Vac truck                          | 1 |   |   |   | Health & Safety | 1 |   |   |   |
|                                    |   |   |   |   |                 |   |   |   |   |

**NYSDEC Site Representative:** Eric S. Knapp

**Date:** June 28, 2004

**Representative's signature:**

**Reviewed By:**

**Date:**

