


# New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Section D



Erin Crotty  
Commissioner

## DAILY INSPECTION REPORT

<b>Site Code #:</b> 7-55-08	<b>Date:</b> July 9, 2004	<b>Report #:</b> NYSEG070904
-----------------------------	---------------------------	------------------------------

**Site Name:** NYSEG Ithaca Court St.

**Location:** Ithaca, Chemung County

**NYSEG Proj. Mgr.:** Bert Finch

**DEC Proj. Mgr.:** Bill Ottaway

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson Environmental

**Site Phone & Fax:**

	AM	PM
<b>Weather</b>	Sunny	Sunny
<b>Temperature</b>	70 degrees	85 degrees
<b>Wind Direction</b>		

### Description of work performed by contr. this report period:

- Continued excavation of Duct #1. Impacted material begins at 3.5 feet bgs (top of duct), down to 9.5 feet bgs. Excavated to 5 feet north of duct (just under sidewalk). Removed a total of 10 feet of duct and storm sewer.
- Sent 3 trucks to ESML.

### Description of inspections performed by engr. this report period:

- Dave Budosh (URS) onsite.

### Discussions/comments regarding visitors, contractor and/or engineer:

•

### Sampling and Analyses:

•

Major Issues	Description & Reason
--------------	----------------------

--	--

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

**Contractor's Information:**

Prime contractor worked from 7:00A to 3:30P.

**Site Representative:** R. Scott Deyette

**Date:** July 9, 2004

**Representative's signature:**