



Erin Crotty  
 Commissioner

**DAILY INSPECTION REPORT**

<b>Site Code #:</b> 7-55-008	<b>Date:</b> September 29, 2004	<b>Report #:</b> NYSEG092904
------------------------------	---------------------------------	------------------------------

**Site Name:** NYSEG Ithaca Court St.- Wooden Duct Removal

**Location:** Ithaca, Tompkins County

**NYSEG Proj. Mgr.:** Bert Finch

**DEC Proj. Mgr.:** Bill Ottaway

**Consultant Proj. Mgr.:** Dave Budosh

**Proj. Contr.:** Severson

**Site Phone & Fax:**

	AM	PM
<b>Weather</b>		
<b>Temperature</b>		
<b>Wind Direction</b>		

**Description of work performed by contr. this report period:**

- No work was done in potentially contaminated areas today. Contractor worked in previously backfilled areas, resetting a new manhole.

**Description of inspections performed by engr. this report period:**

- 

**Discussions/comments regarding visitors, contractor and/or engineer:**

- 

**Change Orders:**

- 

**Sampling and Analyses:**

Major Issues	Description & Reason

**Health & Safety:**

Level of protection: D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone

**Contractor's Information:**

Prime contractor worked from 7:00 a.m. to 5:00 p.m.

Subcontractor	Activity	Hours Worked
ESMI	hauling waste	
Evans	plumbing	

Equipment	P	1	2	3	Personnel	P	1	2	3
Komatsu W140 backhoe, with hoe-ram	1				Supervisor	1			
Komatsu PW170ES excavator	1				Operator	2			
Tractor trailer					Laborer	1			
Loader	1				Teamster				
Vac truck	1				Health & Safety	1			
					Plumber			2	

**NYSDEC Site Representative:** Eric S. Knapp

**Date:** September 29, 2004

**Representative's signature:**

**Reviewed By:**

**Date:**

