

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008**Date:** January 09, 2013**Report #:** NYSEGICS01092013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson drove sheet piling near northwest corner of site in Esty Street.

Contractor had completed razing Markles Flat building. Salvaged materials were stockpiled on site. Floor of building still present and visible.

Discussions/comments regarding visitors, contractor and/or engineer:

Weekly progress meeting was held on site at 11:00 am.

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors Representing Entered Exclusion Zone

Site Representative: Eric Knapp

Date: January 9, 2013

Representative's signature:

