

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** April 25, 2013 **Report #:** NYSEGICS04252013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEGProj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson worked removing sheetpile from the ground surrounding the 1A area, with some delay for reparations to be made to the ABI rig. These piles were cleaned and stockpiled for reuse. Previously stockpiled soils were loaded onto trucks within the sprung structure for transport and disposal at Seneca Meadows. Contractor sprayed Bio-solve as needed during activities to mitigate odors. Water was used on site for dust control. Local roads were cleaned as needed.

Subcontractor Paolangeli replaced water main valve and began replacing water main in Esty Street and restoring water service to homes.

Discussions/comments regarding visitors, contractor and/or engineer:

Scott Deyette on site.

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors Representing Entered Exclusion Zone

Site Representative: Eric Knapp
Representative's signature:

Date: April 25, 2013