

**New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** May 02, 2013 **Report #:** NYSEGICS05022013

**Site Name:** NYSEG Ithaca Court Street MGP

**Location:** Ithaca, NY

**NYSEG Proj. Mgr.:** Tracey Blazicek

**DEC Proj. Mgr.:** Elizabeth Lukowski

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Contractor Severson continued driving sheet piles around area 1B. Contractor sprayed Bio-solve as needed during activities to mitigate odors. Contractor worked backfilling area 1A. Water was used on site for dust control and compaction. Local roads were cleaned as needed. Contractor removed road curbing where needed. City of Ithaca representatives were on site to cap old water main.

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Visitors Representing Entered Exclusion Zone**

**Site Representative:** Eric Knapp  
**Representative's signature:**

**Date:** May 02, 2013