

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** May 09, 2013 **Report #:** NYSEGICS05092013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson removed old foundation from 420 Plain St. Contractor worked backfilling voids. Water was used on site for dust control and compaction. Local roads were cleaned as needed. Contractor did preparation work for installation of temporary utilities to 416 and 418 Plain St.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors Representing Entered Exclusion Zone

Site Representative: Eric Knapp

Date: May 09, 2013

Representative’s signature: