

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** May 10, 2013 **Report #:** NYSEGICS05102013
Site Name: NYSEG Ithaca Court Street MGP
Location: Ithaca, NY
NYSEG Proj. Mgr.: Tracey Blazicek
DEC Proj. Mgr.: Elizabeth Lukowski
Consultant Proj. Mgr.:
Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson uncovered 24" sewer main in Plain St. Contractor worked backfilling excavations. Water was used on site for dust control and compaction. Local roads were cleaned as needed. Contractor received equipment on site.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors Representing Entered Exclusion Zone

Site Representative: Eric Knapp
Representative's signature:

Date: May 10, 2013

