

**New York State Department of Environmental Conservation**  
Division of Environmental Remediation - Central Office  
Remedial Bureau C  
Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** May 16, 2013 **Report #:** NYSEGICS05162013

**Site Name:** NYSEG Ithaca Court Street MGP

**Location:** Ithaca, NY

**NYSEG Proj. Mgr.:** Tracey Blazicek

**DEC Proj. Mgr.:** Elizabeth Lukowski

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Contractor Severson worked with subcontractor Paolangeli to install new valve for water main on Plain St., and to prepare for sewer bypass. Contractor encountered impacted material in northern end of excavation at an approximate depth of 6 feet. Water was used on site for dust control.

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Visitors Representing Entered Exclusion Zone**

**Site Representative:** Eric Knapp  
**Representative's signature:**

**Date:** May 16, 2013