

**New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** May 17, 2013 **Report #:** NYSEGICS05172013

**Site Name:** NYSEG Ithaca Court Street MGP

**Location:** Ithaca, NY

**NYSEG Proj. Mgr.:** Tracey Blazicek

**DEC Proj. Mgr.:** Elizabeth Lukowski

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Contractor Severson worked with subcontractor Paolangeli to prepare for sewer bypass in Plain St.  
Contractor pumped water from excavation as needed. Water was used on site for dust control.

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Representative:** Eric Knapp  
**Representative's signature:**

**Date:** May 17, 2013