

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** May 22, 2013 **Report #:** NYSEGICS05222013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson continued working with subcontractors Metroplitan and Paolangeli to remove existing transite pipe from Plain St. and install sewer bypass. Contractor continued temporary bypass pumping from sewer. Contractor removed an old gas line which contained some impacted water. Water was treated and surrounding soils were placed under cover for future disposal. Contractor pumped water from excavation as needed. Water was used on site for dust control.

Discussions/comments regarding visitors, contractor and/or engineer:

Weekly progress meeting was held on site at 1100.

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: May 22, 2013