

**New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** May 24, 2013 **Report #:** NYSEGICS05242013

**Site Name:** NYSEG Ithaca Court Street MGP

**Location:** Ithaca, NY

**NYSEG Proj. Mgr.:** Tracey Blazicek

**DEC Proj. Mgr.:** Elizabeth Lukowski

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Contractor Severson continued working with subcontractor Paolangeli, completing sewer bypass in Plain St. Contractor continued temporary bypass pumping from sewer. Contractor backfilled where possible. Contractor reopened intersections at both ends of block. Contractor pumped water from excavation as needed. Water was used on site for dust control.

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Representative:** Eric Knapp  
**Representative's signature:**

**Date:** May 24, 2013