

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** May 30, 2013 **Report #:** NYSEGICS05302013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson placed a vibration monitor near 412 Plain. St. Contractor drove sheet piling for cell 1B. Biosolve was used as needed to control odors. Water was used on site for dust control.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: May 30, 2013