

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 10, 2013 **Report #:** NYSEGICS06102013
Site Name: NYSEG Ithaca Court Street MGP
Location: Ithaca, NY
NYSEG Proj. Mgr.: Tracey Blazicek
DEC Proj. Mgr.: Elizabeth Lukowski
Consultant Proj. Mgr.:
Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson excavated top 8 feet of soil from portion of cell 1B at 420 Plain St. Contractor completed connecting new air handling equipment for temporary fabric structure. Water was used on site for dust control.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 10, 2013