

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 11, 2013 **Report #:** NYSEGICS06112013
Site Name: NYSEG Ithaca Court Street MGP
Location: Ithaca, NY
NYSEG Proj. Mgr.: Tracey Blazicek
DEC Proj. Mgr.: Elizabeth Lukowski
Consultant Proj. Mgr.:
Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson excavated soil from cells 1B 1 and 1B2. Contractor worked constructing and installing shoring for cell 1B3. Water was used on site for dust control. Soils were stockpiled for either reuse, or eventual disposal, as appropriate.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 11, 2013