

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 12, 2013 **Report #:** NYSEGICS06122013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Contractor Severson excavated soil from cells 1B 1 and 1B2. Contractor worked constructing and installing shoring for cell 1B3. Water was used on site for dust control. Soils were stockpiled for either reuse, or eventual disposal, as appropriate.

Subcontractor Metropolitan removed some transite pipe from cell 1B.

Discussions/comments regarding visitors, contractor and/or engineer:

Weekly progress meeting held on site at 1100.

Sampling and Analyses:

Major Issues Description & Reason

New air handling system is exhausting carbon dust. Excavation suspended until problems addressed.

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 12, 2013