

**New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** June 13, 2013 **Report #:** NYSEGICS06132013

**Site Name:** NYSEG Ithaca Court Street MGP

**Location:** Ithaca, NY

**NYSEG Proj. Mgr.:** Tracey Blazicek

**DEC Proj. Mgr.:** Elizabeth Lukowski

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Contractor Severson excavated soil from cells 1B 1 and 1B2. Contractor worked constructing and installing shoring for cell 1B3. Biosolve was used to control odors. Water was used on site for dust control. Excavation and stockpiles were foamed when excavation was completed for the day.

Soils were stockpiled for either reuse, or eventual disposal, as appropriate.

Transite pipe was removed from site for disposal..

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

Attempts to fix air handling equipment proved unsuccessful, and excavation was again suspended.

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Representative:** Eric Knapp

**Date:** June 13, 2013

**Representative's signature:**