

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 14, 2013 **Report #:** NYSEGICS06142013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Prime contractor Severson did not excavate today, due to malfunctioning air handling unit.

Biosolve was used to control odors. Water was used on site for dust control. Excavation and stockpiles were foamed.

Air handling equipment was repaired – carbon was added and leveled. Equipment now seems to function appropriately.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 14, 2013