

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 17, 2013 **Report #:** NYSEGICS06172013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Prime contractor Severson excavated today in cell 1B. Biosolve was used to control odors. Water was used on site for dust control. Soils were stockpiled for eventual reuse or disposal, as appropriate. Excavation and stockpiles were foamed.

Discussions/comments regarding visitors, contractor and/or engineer:

A transformer malfunctioned near sight. Power to air handling equipment had to be disconnected to effect a repair. Excavation was temporarily suspended during that time.

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 17, 2013