

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 18, 2013 **Report #:** NYSEGICS06182013
Site Name: NYSEG Ithaca Court Street MGP
Location: Ithaca, NY
NYSEG Proj. Mgr.: Tracey Blazicek
DEC Proj. Mgr.: Elizabeth Lukowski
Consultant Proj. Mgr.:
Proj. Contr.: Severson

Description of work performed by contr. this report period:

Prime contractor Severson completed excavation today in cells 1B1 and 1B2. Biosolve was used to control odors. Water was used on site for dust control. Soils were stockpiled for eventual reuse or disposal, as appropriate. Contractor worked backfilling excavation. Excavation and stockpiles were foamed.

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 18, 2013