

**New York State Department of Environmental Conservation**

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** June 19, 2013 **Report #:** NYSEGICS06192013

**Site Name:** NYSEG Ithaca Court Street MGP

**Location:** Ithaca, NY

**NYSEG Proj. Mgr.:** Tracey Blazicek

**DEC Proj. Mgr.:** Elizabeth Lukowski

**Consultant Proj. Mgr.:**

**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Prime contractor Severson continued backfilling in cells 1B1 and 1B2. Contractor completed excavating in cell 1B3. Contractor began backfilling cell 1B3. Biosolve was used to control odors. Water was used on site for dust control. Soils were stockpiled for eventual reuse or disposal, as appropriate. . Excavation and stockpiles were foamed.

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Representative:** Eric Knapp  
**Representative's signature:**

**Date:** June 19, 2013