

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 20, 2013 **Report #:** NYSEGICS06202013
Site Name: NYSEG Ithaca Court Street MGP
Location: Ithaca, NY
NYSEG Proj. Mgr.: Tracey Blazicek
DEC Proj. Mgr.: Elizabeth Lukowski
Consultant Proj. Mgr.:
Proj. Contr.: Severson

Description of work performed by contr. this report period:

Prime contractor Severson removed bracing from cell 1B3 and completed backfilling cell.
Biosolve was used to control odors. Water was used on site for dust control

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 20, 2013