

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 24, 2013 **Report #:** NYSEGICS06242013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Prime contractor Severson continued backfilling and compacting in cells 1B1 and 1B2.

Contractor loaded stockpiled soil onto trucks for transport and disposal at Seneca Meadows Landfill. Water was used on site for dust control

Discussions/comments regarding visitors, contractor and/or engineer:

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 24, 2013