

New York State Department of Environmental Conservation
Division of Environmental Remediation - Central Office
Remedial Bureau C
Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** June 26, 2013 **Report #:** NYSEGICS06262013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Prime contractor Severson loaded stockpiled soil onto trucks for transport and disposal at ESMI.
Contractor worked removing sheetpile from 1B. ABI rig required some amount of
downtime for repair. Water was used on site for dust control

Discussions/comments regarding visitors, contractor and/or engineer:

Weekly progress meeting held on site at 1100.

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: June 26, 2013