

**New York State Department of Environmental Conservation**  
Division of Environmental Remediation - Central Office  
Remedial Bureau C  
Inspection Unit

**DAILY INSPECTION REPORT**

**Site Code #:** 755008 **Date:** June 27, 2013 **Report #:** NYSEGICS06272013  
**Site Name:** NYSEG Ithaca Court Street MGP  
**Location:** Ithaca, NY  
**NYSEG Proj. Mgr.:** Tracey Blazicek  
**DEC Proj. Mgr.:** Elizabeth Lukowski  
**Consultant Proj. Mgr.:**  
**Proj. Contr.:** Severson

**Description of work performed by contr. this report period:**

Prime contractor Severson loaded stockpiled soil onto trucks for transport and disposal at ESMI.  
Contractor worked removing sheetpile from 1B. ABI rig required some amount of  
downtime for repair. Water was used on site for dust control

**Discussions/comments regarding visitors, contractor and/or engineer:**

**Sampling and Analyses:**

**Major Issues Description & Reason**

Some significant damage to foundation of house #418 Plain St. noted.

**Health & Safety:**

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List deviations.

Are atmospheric monitoring results acceptable? Yes.

**Site Representative:** Eric Knapp  
**Representative's signature:**

**Date:** June 27, 2013