

New York State Department of Environmental Conservation

Division of Environmental Remediation - Central Office

Remedial Bureau C

Inspection Unit

DAILY INSPECTION REPORT

Site Code #: 755008 **Date:** October 21, 2013 **Report #:** NYSEGICS10212013

Site Name: NYSEG Ithaca Court Street MGP

Location: Ithaca, NY

NYSEG Proj. Mgr.: Tracey Blazicek

DEC Proj. Mgr.: Elizabeth Lukowski

Consultant Proj. Mgr.:

Proj. Contr.: Severson

Description of work performed by contr. this report period:

Ithaca City work crew excavating in Esty Street adjacent to Court St. site, for the purpose of replacing a water main. Excavation between four and five feet deep and two feet wide. There is no sign of staining or contamination in soils. There are some odors associated with paving material. All excavated soils and piping are being removed and replaced with imported fill. Work today occurred between 112 Esty and 108 Esty.

Discussions/comments regarding visitors, contractor and/or engineer:

Two local residents stopped to ask questions about the work and about the Court Street site. One requested contact information for Tracy Blazicek of NYSEG, which he was given. Air monitoring was in place throughout work activities.

Sampling and Analyses:

Major Issues Description & Reason

Health & Safety:

Level of protection: Modified Level D.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.
List deviations.
Are atmospheric monitoring results acceptable? Yes.

Site Representative: Eric Knapp
Representative's signature:

Date: October 21, 2013