



**Groundwater
& Environmental Services, Inc.**

300 Gateway Park Drive • North Syracuse, New York 13212 • 800-220-3069 • Fax 315-452-3237

September 3, 2010

Mr. Vivek Nattanmai, P.E.
Division of Environmental Remediation
NYSDEC
625 Broadway
Albany, New York 12233-7013

**Re: Site Photo Log
Trimmer Road Landfill Site #8-28-012
Parma, New York**

Dear Mr. Nattanmai,

Please find attached a photo log documenting initial site activities at the Trimmer Road Landfill Site in Parma, New York. On behalf of NYSDEC, Groundwater & Environmental Services, Inc. (GES) completed the following activities at the site:

- **July 29, 2010:** Installation of passive diffusion bags (PDBs) into select monitoring wells (MW-4s, MW-5s, MW-6s, MW-8s, MW-9s, MW-13, MW-14, MW-15, MW-16, MW-17, MW-18 and MW-19).
- **August 25, 2010:** Completed site mowing of all three vegetative buffers and collection of groundwater samples from PDBs installed in MW-4s, MW-5s, MW-6s, MW-8s, MW-9s, MW-13, MW-14, MW-15, MW-16, MW-17, MW-18 and MW-19.

In addition to the summary of photos in the attached log, a CD of high-resolution digital photos is enclosed. If you have any questions about these activities or the photo documentation please feel free to contact GES at 800-220-3069.

Sincerely,
GROUNDWATER & ENVIRONMENTAL SERVICES, INC.

Kenneth Hubbard
Hydrogeologist

Justin Domago
Hydrogeologist / Project Manager

Attachment: Photo Log
Enclosure: Photo CD



Photo #1: July 29, 2010 – PDB install at MW-4s.



Photo #2: July 29, 2010 – PDB install at MW-4s complete.



Photo #3: July 29, 2010 – PDB install at MW-17.



Photo #4: July 29, 2010 – PDB install at MW-17 complete.



Photo #5: July 29, 2010 – PDB install at MW-6s.



Photo #6: July 29, 2010 – PDB install complete at MW-6s.



Photo #7: July 29, 2010 – PDB install at MW-16.



Photo #8: July 29, 2010 – PDB install complete at MW-16.



Photo #9: July 29, 2010 – PDB install at MW-5s.



Photo #10: July 29, 2010 – PDB install complete at MW-5s.



Photo #11: July 29, 2010 – PDB install at MW-9s.



Photo #12: July 29, 2010 – PDB install complete at MW-9s.



Photo #13: July 29, 2010 – PDB install at MW-8s.



Photo #14: July 29, 2010 – PDB install complete at MW-8s.



Photo #15: July 29, 2010 – PDB install at MW-18.



Photo #16: July 29, 2010 – PDB install complete at MW-18.



Photo #17: July 29, 2010 – PDB install at MW-13.



Photo #18: July 29, 2010 – PDB install complete at MW-13.



Photo #19: July 29, 2010 – PDB install at MW-15.



Photo #20: July 29, 2010 – PDB install complete at MW-15.



Photo #21: July 29, 2010 – PDB install at MW-19.



Photo #22: July 29, 2010 – PDB install complete at MW-19.



Photo #23: July 29, 2010 – PDB install at MW-14.



Photo #24: July 29, 2010 – PDB install complete at MW-14.



Photo #25: August 25, 2010 – Vegetative buffer #1 prior to site mowing.



Photo #26: August 25, 2010 – Vegetative buffer #3 prior to site mowing.



Photo #27: August 25, 2010 – Vegetative buffer #1 following site mowing.



Photo #28: August 25, 2010 – Vegetative buffer #2 following site mowing.



Photo #29: August 25, 2010 – Vegetative buffer #3 following site mowing.