

Inactive Hazardous Waste Site Operations and Maintenance Review Report

Form Date 9-10-

Site Name: TAYLOR Instruments		Class: 4	Number: 828028a															
O&M Funding Source:	☐ State Superfund	☐ Federal Superfund	☐ Municipal ☐ Responsible Party															
O&M Information:	O&M Start:	End:	Annual Cost: \$ ☐ Estimated															
Interim Remedial Measures/Operable Units in O&M Phase: <table border="0" style="width:100%"><tr><td>☐ Drum Removal</td><td>☐ Soil Removal</td><td>☐ Tank Removal</td></tr><tr><td>☒ Cap/Cover</td><td>☐ Containment Structure</td><td>☐ Fence/Security</td></tr><tr><td>☐ Groundwater Recovery/Treatment</td><td>☐ Leachate Collection/Treatment</td><td>☐ Vapor Extraction/Treatment</td></tr><tr><td>☐ Air Sparging/Stripper System</td><td>☐ Treatment/Filtration Plant/System</td><td>☐ Potable Water Supply/System</td></tr><tr><td>☐ Other:</td><td></td><td></td></tr></table>				☐ Drum Removal	☐ Soil Removal	☐ Tank Removal	☒ Cap/Cover	☐ Containment Structure	☐ Fence/Security	☐ Groundwater Recovery/Treatment	☐ Leachate Collection/Treatment	☐ Vapor Extraction/Treatment	☐ Air Sparging/Stripper System	☐ Treatment/Filtration Plant/System	☐ Potable Water Supply/System	☐ Other:		
☐ Drum Removal	☐ Soil Removal	☐ Tank Removal																
☒ Cap/Cover	☐ Containment Structure	☐ Fence/Security																
☐ Groundwater Recovery/Treatment	☐ Leachate Collection/Treatment	☐ Vapor Extraction/Treatment																
☐ Air Sparging/Stripper System	☐ Treatment/Filtration Plant/System	☐ Potable Water Supply/System																
☐ Other:																		
Institutional Controls:	☐ Deed Restriction	☐ Discharge Permit	☐ Department of Health Sampling ☐ Other:															
O&M Review Information: Reports: Misc. reports submitted by ABB (current owner) Inspection: Site Visit - Bob Long - DATE: 3/5/98 Sampling: Other:																		
Conclusions: Remedy Effective? ☐ Yes ☒ No ROD Compliance? ☐ Yes ☐ No: Consent Order Compliance? ☐ Yes ☐ No: Other:																		
Recommendations: UCA signed agreement Some negotiations continue. If unable to come to agreement with PRP-volunteer, then reclassify entire site to class 2.																		
POD/Consent Order Modifications? ☐ No ☐ Yes (see above) Reclassify the Site? ☒ No ☒ Yes → Class. 2 Comments: NOT AT THIS TIME																		
Project Manager: Signature: [Signature] Date: 3/5/98 Name: DAVID G. BRATT Region or Bureau: reg. 8 Telephone: 716/226-2466		Reviewer: Signature: Mary Jane Peachey Date: 3/5/98 Name: Mary Jane Peachey Region or Bureau: 716/226-2466 Telephone:																

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF HAZARDOUS WASTE REMEDIATION
INSPECTOR'S DAILY REPORT

Site Code No. 828028 A
Site Name: TAYLOR INSTRUMENTS
Location: ROCHESTER (C) MONROE (Co)
Engineer: —
Contractor: —
Job Phone: () —

Date 3/5/98 I.R. No. Om

Sheet 1 of 1

	AM	PM
Weather	<u>Part. Cloudy</u>	
Temperature	<u>28</u>	<u>33</u>
Wind (Dir. & Vel.)	<u>out of NW</u>	

Health & Safety:

Level of protective clothing used: N/A

Is the level of protection in conformance with the approved Health & Safety Plan?

Yes — No — If no, list the deviations under Items of Concern.

Are atmospheric monitoring results at acceptable levels? Yes — No —

Attach a copy of the monitoring log.

N/A

Description of work performed during this report period:

95 AMES STREET —

AREA OF CONCERN IS COVERED WITH ASPHALT.

AREA IS RESTRICTED (NO PARKING) AND IS SECURED (LOCKED GATES / FENCE)

TWO (2) EMPTY HOLDING TANKS ARE STAGED ON EAST SIDE

SEVERAL SOIL PILES ARE STAGED ON THE PARKING LOT AND ARE COVERED W/ POLY — NEEDS TO BE REPLACED.

Site Visitors

Representing

Entered exclusion zone