

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

	Form Date 96.10.0
Site Name: Taylor Instruments Class:	4 Number: 828028a
O&M Funding Source: State Superfund Federal Superfund	Municipal X Responsible Party
O&M Information: O&M Start: 1999 End:	Annual Cost: \$
Interim Remedial Measures/Operable Units in O&M Phase:	
Drum Removal Soil Removal	Tank Removal
Cap/Cover Containment Structure	X Fence/Security
X Groundwater Recovery/Treatment 🛛 Leachate Collection/Treatment	Vapor Extraction/Treatment
□ Air Sparging/Stripper System □ Treatment/Filtration Plant/System	n 🛛 Potable Water Supply/System
X Other: Dual phase vapor extraction	
Institutional Controls: Deed Restriction X Discharge Permit	Department of Health Sampling
□ Other:	
O&M Review Information:	
Reports: Quarterly Progress Reports	
Inspection: 10/11/2002 Site Visit by David Pratt	
Sampling:	
Conclusions:	
Remedy Effective? X Yes	
ROD Compliance? □ Yes □ No: N/A - VCA compliance √	
Consent Order Compliance? Ves No: N/A - VCA compliance	
Other:	
Recommendations: Continue O&M	
ROD/Consent Order Modifications? X No Yes (per above) Reclassify t	he Site? X No □ Yes → Class:
Comments: Data Usability Summary currently being generated by Voluntee	r. Final Engineering Report under review.
Project Manager: , Revjøwer/ /	4
REG. M 11/25/02 15 PT 11	11-25-02
Signature Date Signature Date Signature Signature Signature	Date Putzig, P.E. Region 8 595/226-5349
David Flatt, F.E. Region or Bureau Telephone Dartholimew F Name Region or Bureau Telephone Name	Region or Bureau Telephone