

APPENDIX I



Photo 1: View looking west of steel plate covering abandoned UST access hatch/fill port on the south end of Building D.



Photo 2: Closer view of access hatch/fill port rim beneath rubble.