

<b>PROJECT:</b>	1000 Turk Hill Road (Site No. 828161)
<b>ADDRESS:</b>	1000 Turk Hill Road, Fairport, Monroe County, New York
<b>PREPARED BY:</b>	Roux Environmental Engineering and Geology, D.P.C.
<b>DATE:</b>	May 26, 2026
<b>WEATHER:</b>	Temp: 80°F Cloudy, Pressure: 29.46" Hg Wind: WSW @ 12 mph

**Remedial Action Work Summary**

Work Activities Performed Onsite:

- Mobilization of personnel and equipment.
- Pre-sampling gauging of monitoring wells associated with this sampling event.
- Low flow groundwater sampling from monitoring wells MW-8S, MW-27S, MW-10S, MW-7S, MW-28S and MW-29S.

**Groundwater Sampling Summary**

Well	Analysis
MW-8S	Volatiles via EPA 8260D + TICs and geochemistry (methane, ethane, ethene, total organic carbon, nitrate/nitrite, sulfate, and carbon dioxide).
MW-27S	
MW-10S	
MW-7S	
MW-28S	
MW-29S	

**Site Map**

