

PROJECT:	1000 Turk Hill Road (Site No. 828161)
ADDRESS:	1000 Turk Hill Road, Fairport, Monroe County, New York
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	May 27, 2026
WEATHER:	Temp: 70°F Sunny, Pressure: 29.33" Hg Wind: NW @ 12 mph

Remedial Action Work Summary

Work Activities Performed Onsite:

- Low flow groundwater sampling from monitoring wells MW-2S, MW-2D, MW-16S, MW-9S, MW-35M, MW-6M, and MW-6D (with duplicates collected from MW-6D and MW-35M).

Groundwater Sampling Summary

Well	Analysis
MW-2S	Volatiles via EPA 8260D + TICs, geochemistry (methane, ethane, ethene, total organic carbon, nitrate/nitrite, sulfate, and carbon dioxide), and bio analysis (DHC).
MW-16S	
MW-9S	
MW-35M	
MW-6M	Volatiles via EPA 8260D + TICs and geochemistry (methane, ethane, ethene, total organic carbon, nitrate/nitrite, sulfate, and carbon dioxide)
MW-6D	
MW-2D	

Site Map

