

PROJECT:	1000 Turk Hill Road (Site No. 828161)
ADDRESS:	1000 Turk Hill Road, Fairport, Monroe County, New York
PREPARED BY:	Roux Environmental Engineering and Geology, D.P.C.
DATE:	May 28, 2026
WEATHER:	Temp: 60°F Cloudy, Pressure: 29.50" Hg Wind: NNW @ 14 mph

Remedial Action Work Summary

Work Activities Performed Onsite:

- Low flow groundwater sampling from monitoring wells MW-11M, MW-11D, MW-11S, MW-3S, MW-15S, MW-5S, and MW-2M.
- Demobilization of personnel and equipment.
- Property owner was observed doing emergency drainage work between Buildings 1 and 2.

Groundwater Sampling Summary

Well	Analysis
MW-11M	Volatiles via EPA 8260D + TICs and geochemistry (methane, ethane, ethene, total organic carbon, nitrate/nitrite, sulfate, and carbon dioxide).
MW-11D	
MW-11S	
MW-3S	
MW-15S	
MW-5S	
MW-2M	

Site Map

