

Perform Annual PCB O&M Site Inspec... - Associated With [Clifton Springs CS 237 Remediation]**Details****Description**

For the previous calendar year, complete by May 31st of the current year, the inspection of the retired burn pit area capped area. The inspection of the soil and gravel cap will be performed in the spring of each year to ensure the integrity of the cap is maintained and functioning as intended. If inadequacies are identified it is to be restored in a manner consistent with its original

Responsible Function

View Citations

**Go****Responsible Individual**

URL

None

Responsible Manager

Due Date

Date Completed

 05 01 2017
 05 01 2017
 05 01 2017

Activities

Deviation Status

Completion Status

Last Modified By

What does Open-Exception mean?

What does Closed-Exception mean?

What does Complete Successful mean?

What does Closed Not Applicable mean?

Completion Comment (Required for all Closed - Exception, Open - Exception, and Closed - Not Applicable completion statuses)

Assigned Assets

Name	Type
No Assets Found.	

Page 1 of 0 [Total 0]

Reference Documentation

Title	Filename	Description
No Documents Found.		

Page 1 of 0 [Total 0]

Completion Documentation

Title	Filename	Description	Upload Date	File Size
No Documents Found.				

Page 1 of 0 [Total 0]

Perform Annual PCB O&M Site Inspec... - Associated With [Clifton Springs CS 237 Remediation]**Details****Description**

For the previous calendar year, complete by May 31st of the current year, the inspection of the retired burn pit area capped area. The inspection of the soil and gravel cap will be performed in the spring of each year to ensure the integrity of the cap is maintained and functioning as intended. If inadequacies are identified it is to be restored in a manner consistent with its original

Responsible Function

View Citations

**Go**
Responsible Individual

URL

None

Responsible Manager

Due Date

Date Completed

**Activities**

Deviation Status

Completion Status

Last Modified By

What does Open-Exception mean?

What does Closed-Exception mean?

What does Complete Successful mean?

What does Closed Not Applicable mean?

Completion Comment (Required for all Closed - Exception, Open - Exception, and Closed - Not Applicable completion statuses)

Assigned Assets

Name	Type
No Assets Found.	
Page 1 of 0 [Total 0]	

Reference Documentation

Title	Filename	Description
No Documents Found.		
Page 1 of 0 [Total 0]		

Completion Documentation

Title	Filename	Description	Upload Date	File Size
No Documents Found.				
Page 1 of 0 [Total 0]				

Perform Annual PCB O&M Site Inspec... - Associated With [Clifton Springs CS 237 Remediation]**Details****Description**

For the previous calendar year, complete by May 31st of the current year, the inspection of the retired burn pit area capped area. The inspection of the soil and gravel cap will be performed in the spring of each year to ensure the integrity of the cap is maintained and functioning as intended. If inadequacies are identified it is to be restored in a manner consistent with its original

Responsible Function

NY-Clifton Springs CS 237 Remediation

View Citations

Select Citation



Go

Responsible Individual**URL**

None

Responsible Manager

NY-Clifton Springs CS 237 Remediation

Due Date

05/31/2015

Date Completed

05/15/2015

**Activities**

None

Deviation Status

Not Marked

Completion Status

Complete - Successful

Last Modified By

Scott Lewis

What does Open-Exception mean?

What does Closed-Exception mean?

What does Complete Successful mean?

What does Closed Not Applicable mean?

Completion Comment (Required for all Closed - Exception, Open - Exception, and Closed - Not Applicable completion statuses)

Assigned Assets

Name	Type
No Assets Found.	
Page 1 of 0 [Total 0]	

Reference Documentation

Title	Filename	Description
No Documents Found.		
Page 1 of 0 [Total 0]		

Completion Documentation

Title	Filename	Description	Upload Date	File Size
No Documents Found.				
Page 1 of 0 [Total 0]				

Perform Annual PCB O&M Site Inspec... - Associated With [Clifton Springs CS 237 Remediation]**Details****Description**

For the previous calendar year, complete by May 31st of the current year, the inspection of the retired burn pit area capped area. The inspection of the soil and gravel cap will be performed in the spring of each year to ensure the integrity of the cap is maintained and functioning as intended. If inadequacies are identified it is to be restored in a manner consistent with its original

Responsible Function

View Citations

**Go****Responsible Individual**

URL

None

Responsible Manager

Due Date

Date Completed

**Activities**

Deviation Status

Completion Status

Last Modified By

What does Open-Exception mean?

What does Closed-Exception mean?

What does Complete Successful mean?

What does Closed Not Applicable mean?

Completion Comment (Required for all Closed - Exception, Open - Exception, and Closed - Not Applicable completion statuses)

Assigned Assets

Name	Type
No Assets Found.	
Page 1 of 0 [Total 0]	

Reference Documentation

Title	Filename	Description
No Documents Found.		
Page 1 of 0 [Total 0]		

Completion Documentation

Title	Filename	Description	Upload Date	File Size
No Documents Found.				
Page 1 of 0 [Total 0]				



Tennessee Gas Pipeline
Company, L.L.C.
a Kinder Morgan company

May 28, 2013

Mr. James Craft
New York State Department of Environmental Conservation
Region 8 Office
6274 East Avon-Lima Road
Avon, NY 14414

RE: Annual Documentation of Operation & Maintenance Activities Station 237 – Site Number 8-35-011

Dear Mr. Craft:

Inspections as specified in Section 3 of the approved O&M plan were conducted at Tennessee Gas Pipelines Station 237 located in Clifton Springs, New York on May 23, 2013.

Per Section 3.3 of the plan, an inspection of the soil and gravel cap was performed to ensure the integrity of the cap is maintained and that it is functioning as intended. Observations from the inspection revealed no integrity issues or any growth of tree saplings on the soil and gravel cap area.

Should you have any questions, please contact me at (724) 662-6436.

Sincerely,

Scott J. Lewis
Specialist – EHS SR II

Cc: Tom Sutton (TGP – Station 229 via e-mail)
Ray Sauvage (TGP – Houston via e-mail)
Phil Wilson (TGP – Station 237)

June 1, 2012

Mr. James Craft
New York State Department of Environmental Conservation
Region 8 Office
6274 East Avon-Lima Road
Avon, NY 14414

RE: Annual Documentation of Operation & Maintenance Activities Station 237 – Site Number 8-35-011


Dear Mr. Craft:

Inspections as specified in Section 3 of the approved O&M plan were conducted at Tennessee Gas Pipelines Station 237 located in Clifton Springs, New York on May 30, 2012.

Per Section 3.3 of the plan, an inspection of the soil and gravel cap was performed to ensure the integrity of the cap is maintained and that it is functioning as intended. Observations from the inspection revealed no integrity issues or any growth of tree saplings on the soil and gravel cap area.

Should you have any questions, please contact me at (724) 662-6436.

Sincerely,



Scott J. Lewis
Principal Environmental Representative

Cc: Tom Sutton (TGP – Station 229 via e-mail)
Ray Sauvage (TGP – Houston via e-mail)
Phil Wilson (TGP – Station 237)