


New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT

Date: October 6 and 8, 2009
Site Name: Patton's Busy Bee
Site Number: 902014
Location: Alfred Station, Allegany County
Project Engineer: Michael J. Hinton, NYSDEC - Buffalo
OM&M Project Manager: Brian P. Sadowski, NYSDEC - Buffalo
Contractor: None

Weather: Mostly Sunny ~60 degrees F on 10/6/09 and Partly Sunny ~53 degrees F.

Purpose of Visit/Inspection: Long Term Monitoring (LTM).

Work Performed/Observations: October 6, 2009.

1015: Brian Sadowski and Tim Dieffenbach arrive on site. Dave Szymanski on at 1030. Commence purging of thirteen monitoring wells in preparation to sample for volatiles and metals. Groundwater was removed at all wells of three well volumes or to minimal recovery. Purge completed at 1420. Personnel off site at 1430.

Work Performed/Observations: October 8, 2009.

1055: Brian Sadowski and Dave Szymanski arrive on site. Grab samples at the following times and locations for Volatiles 8260 and Metals 6010.

1101: MW-113
1113: MW-107S
1118: MW-107I
1140: MW-101D
1145: MW-101I (low GW recovery, grab one-half volume for metals)
1205: MW-103I
1210: MW-103I (MW-110 blind)
1215: MW-103D
1215: MW-103D MS/MSD
1230: MW-104I
1235: MW-104D
1252: MW-102
1301: MW-109
1315: MW-108D
1320: MW-108I
1325: MW-101I (return, complete volume)

Comments: New bailer line needed at MW-101I. Lock maintenance needed at MW-103I. Leachate tanks BB-T1-South, full. BB-T1-North, empty. BB-T2 North and South, empty. No additional evidence of vandalism to gate noticed. Site vegetation was mowed and appeared healthy. No signs of erosion were observed on the cap or cap/toe interface. Site access, tank access and perimeter roads were clear and passable. Samples delivered to Test America by Dave Szymanski at 1737 on October 8, 2009. LTM program completed for 2009. Next LTM planned for October 2011.

Report by: Brian P. Sadowski
Date: October 14, 2009.

Distribution: Mr. Gregory P. Sutton, Mr. Michael J. Hinton, file, e-doc.

Attachments: Pictures.



Cap Vegetation (typ).JPG



MW-101I.JPG



MW-102D Purge Start.JPG
Patton's Busy Bee 100609 LTM



MW-113 Purge Start.JPG
Page 1



Sample Grab.JPG



Site Entrance.JPG

