

**New York State - Department of Environmental Conservation
Division of Environmental Remediation
Periodic Review Evaluation Report**

Period covered by -- 2007-08

Site Code: 905004	Site Name: Moench Tanning	Class: 04
Program Lead: State Superfund Program	Site Management Funding Source: Responsible Party (RP)	
Start Date: 01/01/1992 ACT		
IC/EC Certification:	Recieved Date:	Accept Date:
DEC Inspection Date: 03/31/2008 --- Last Date of DEC Inspection		
Report Used for Evaluation: Longterm Monitoring, Inspection		
ROD Complicance? Yes		
Long Term Monitoring (effectiveness of remedy): Yes Frequency:		
Treatment System (Monitoring performance of remedy): No Frequency: Number of Wells:		
Problem Status:		
Comments/Changes/Attachments: The remedy and O&M requirements: consolidation of waste, surface contour grading, surface water drainage control, stream bank stabilization and capping of existing landfill. O&M consists of cap inspection, mowing, groundwater monitoring and 5 year cap evaluation study. Stan Radon(RCRA) receives and reviews reports, and attends Site inspection (last on 3/31/2008). Noted there are no problems with the site. Some slight gw contamination has been reported in the past. The site has a fence except for the creek area. ROD/Consent Order Modifications? No Site reclassification recommended:		
Contaminant of concern	OU	Media/Receptor
SPRAY BOOTH WASTES (D001) &(D008)	01	
Evaluation: The Remedy is performing properly and is effective.		
Remedies	OU	Site of Treatment
		Date in Place
		Remedy Effective

Next Review:	Priority: 01
Project Manager: DSSZYMAN	Reviewer: MLDOSTER
Signature: _____ Date: _____	Signature: _____ Date: _____
Name _____ Region or Bureau _____ Telephone _____	Name _____ Region or Bureau _____ Telephone _____

☒ SM Certified
All Data Entered