

Date: 1/29/15

Technician: Joe Goodfellow

Customer: Horizon Environmental Services

Site Address: Willowbrook Ave. Dunkirk, N.Y.

Contact Person: Brian Spangler Phone: 412-303-8692 Phone: _____

Scope of Work: Clear 120 linear feet for new utility installation

Type of Service:

- Leak Detection* *Utility Location/GPR* *Video Inspection*
 Infrastructure Assessment *Utility Mapping/AutoCAD*

Type of Equipment Used

- Profiler EMP 400* *RD4000* *MetroTech Vivax vLocPro2*
 LC2500 Leak Correlator *Noggin 250 mHz* *PosiTector UTG G3*
 S-30 Surveyor *Noggin 500 mHz* *Video Inspection Camera*
 Sonde *Conquest 1000 mHz* *Helium #* *Bottles*
 Leica Robotic Total Station *Leica GPS*

Marking Used

- Paint* *Flags* *Chalk*
 Updated existing maps onsite *Other:*

Instructions from Onsite Contact: Locate 2" gas service and clear area for new storm drain pipe from pond to Willowbrook Creek.

Size of Pipe: _____

Notes/Testing Results: Located storm and sanitary lines in the area of excavation - poor reception and anomalies with wires and debris around. 150' to the east located gas line 3' down. Gave window from elevation maker 627.25 to the north 9' to 25' where gas line should be. Dig with caution in this area. See attached photos..

Information Transfer

- Information relayed on site to: Office* *Hand drawn map (forward to office for digital remake)* *All markings picked up by surveyors*

Key

Blue	Water
Red	Power
Orange	Communications
Yellow	Gas/Flammable Fuel
White	Unknown
Green	Storm/Sanitary









