



SITE INSPECTION REPORT

Site Name: Lexington Machining LLC

Site Number: 907044

Location: 201 Winchester Road, Lakewood, NY 14750

Inspection Date: 6/16/2026

NYSDEC Project Manager: Bradley Demo

Weather Conditions: Sunny, warm, 65°F

Personnel Onsite: Tim (**Apex Companies**) 2 drillers (**Wertz Geotechnical**)


Description of Work Performed: Dye test for groundwater injections

- Wertz was setup at monitoring well MW-9 with 1 injection well and 2 observation wells marked.
- Wertz augured through concrete at first injection well and switched to direct push using Geoprobe 7822 DT. Refusal was hit at ≈15 fbgs after several minutes at the same location. The intended screened interval of 13-18 fbgs could not be achieved.
- After several discussions between Apex, Wertz and injections workplan designer Regensis the choice was made to stop work for the day and reassess the approach of the dye test and possibly the injections design. NYSDEC informed Apex an addendum to the workplan would need to be approved prior to that work occurring. Rods were dry upon borehole removal indicating water bearing zone had not been reached. Borehole was backfilled and sealed.
- Site is in compliant condition. No evidence of change of use, excavation, or physical alteration. Injection wells at rear of building remain capped. Building remains unoccupied.

Inspector: Bradley Demo

Signature:

Photolog:



Auguring concrete at MW-9 injection well.

Site Inspection Report

Lexington Machining LLC (Site 907044)

June 16, 2026

Page 3



Point for direct push rod used.

Site Inspection Report

Lexington Machining LLC (Site 907044)

June 16, 2026

Page 4



Drill rig.



Site conditions facing E.

Site Inspection Report

Lexington Machining LLC (Site 907044)

June 16, 2026

Page 6



Site conditions facing NW.

Site Inspection Report

Lexington Machining LLC (Site 907044)

June 16, 2026

Page 7



Site conditions/capped injections wells facing W.

Site Inspection Report

Lexington Machining LLC (Site 907044)

June 16, 2026

Page 8



Site conditions facing S.

Site Inspection Report

Lexington Machining LLC (Site 907044)

June 16, 2026

Page 9



Sealed borehole/attempted injection well.