

DUNLOP TIRE CORPORATION

LANDFILL CONDITION - QUARTERLY INSPECTION REPORT

Site No.: 915018 A, B & C

Date of Inspection: 6/01/05

SEMI-ANNUAL

Name of Inspector:

M. CRAFT - DUNLOP
BRIAN SADOWSKI - NYS DEC

	Topsoil Erosion Occurring?	Clay Cap Erosion Occurring?	Ditches free of obstruction?	Grass cover adequate?	Paved areas intact?	Note any damage.
AREA "B"						
Southern Area	N	N	Y	Y		- NONE
Northern Area	N	N	Y	Y		- "
River Road Ditch	N	N	Y	Y		- "
BORROW PIT						
	N	N/A	N/A	N/A		- NONE
AREA "A"						
Central Area	N	N	Y	Y		- NONE
Northeast Area	N	N	Y	Y		"
AREA "C"						
Outlying Area	N	N	Y	Y		- NO DAMAGE
Major Area	N	N	Y	Y		- GOOD GRASS COVERAGE
Ditch at toe of slope	N	N	Y	Y		(LAWN MOWING IN PROCESS)
Sheridan Drive Ditch	N	N	Y	Y		"
Stockpile Area	N	N	Y	Y		"
Warehouse ditch	N	N	Y	Y		"
PAVED AREAS						
Parking lot					Y	NONE
Driveway					Y	"

WEATHER CONDITIONS:

Temperature	80
Wind Direction	SW
Wind Speed	10
Precipitation Amount	0
Sky Conditions	CLEAR
Inches of Snow Cover	0

Describe any corrective action required:

NO CORRECTIVE ACTION REQ'D
- ALL SITES LOOKED GOOD

Describe any corrective action taken:

N/A

M. Craft 7/14/05

DUNLOP TIRE CORPORATION

LANDFILL CONDITION - QUARTERLY INSPECTION REPORT

Site No.: 915018 A, B & C





















SEMI-ANNUAL

Date of Inspection:

7/11/06

Name of Inspector:

BRIAN SADOWSKI, DEC
MARK CRAFT, GOTMA

	Topsoil Erosion Occurring?	Clay Cap Erosion Occurring?	Ditches free of obstruction?	Grass cover adequate?	Paved areas intact?	Note any damage.
AREA "B"						
Southern Area	N	N	Y	Y		NONE
Northern Area	N	N	Y	Y		NONE
River Road Ditch	N	N	Y	Y		NONE
BORROW PIT						
AREA "A"	N	N/A	N/A	N/A		NONE
Central Area	N	N	Y	Y		NONE
Northeast Area	N	N	Y	Y		NONE
AREA "C"						
Outlying Area	N	N	Y	Y		NO DAMAGE
Major Area	N	N	Y	Y		" "
Ditch at toe of slope	N	N	Y	Y		" "
Sheridan Drive Ditch	N	N	Y	Y		" "
Stockpile Area	N	N	Y	Y		" "
Warehouse ditch	N	N	Y	Y		" "
PAVED AREAS						
Parking lot					Y	NO DAMAGE
Driveway					Y	" "

WEATHER CONDITIONS:

Temperature	80° F
Wind Direction	SW
Wind Speed	5-10
Precipitation Amount	0
Sky Conditions	CLEAR
Inches of Snow Cover	N/A

Describe any corrective action required:

NO CORRECTIVE ACTION REQ'D
ALL AREAS IN GOOD CONDITION

Describe any corrective action taken:

N/A